



POLIAS BUCHA QD

Faça download de nossos desenhos padrões.

Dimensões padrões para construção de buchas QD 'Quick Dismounting'.



TIPO	A	B	D	E	F	G	L	ØMIN.	ØMAX
QT	6,40	41,28	63,50	25,40	22,20	3,20	31,80	12,00	30,00
JÁ	8,0	34,92	50,8	15,8	11,00	4,8	25,4	12,0	25,0
H	8,0	41,27	63,5	23,8	20,60	3,2	31,8	12,0	25,0
SH	9,5	47,60	68,3	22,2	17,42	4,8	31,7	12,0	35,0
SDS	11,0	55,55	81,0	22,2	17,42	4,8	33,2	12,0	40,0
SD	11,0	55,65	81,0	35,0	29,40	5,6	46,0	12,0	40,0
SDU	12,7	63,60	90,0	34,9	29,30	5,6	47,6	12,0	48,0
SK	12,7	71,51	98,4	34,9	29,30	5,6	47,6	12,0	60,0
SF	12,7	79,45	117,5	38,1	32,50	5,6	65,0	12,0	65,0
SFU	16,0	94,00	140,0	44,0	37,50	6,5	80,0	12,0	70,0
E	19,0	97,38	152,4	47,6	40,20	7,4	66,6	19,0	70,0
F	20,6	112,80	168,3	71,4	64,00	7,4	92,0	19,0	82,0
J	25,4	130,78	184,0	88,0	80,60	7,4	114,3	25,0	95,0
JU	25,4	136,77	186,0	116,6	109,20	7,4	142,0	25,0	105,0
M	32,0	165,00	228,6	139,5	131,30	8,2	171,5	30,0	120,0
N	38,1	177,60	254,0	168,7	158,50	10,2	206,4	40,0	150,0
P	44,5	209,35	298,5	193,7	183,50	10,2	238,2	40,0	175,0
W	51,0	265,10	381,0	238,0	227,80	10,2	289,0	40,0	215,0